

Haddonfield High School

Date	Location	Sample Type	Result	Clearance Criteria
6/20/2017	Stadium Maint Stairwell	PCM Air	< 0.001 Fibers/cc	0.010 fibers/cc
6/20/2017	Stadium Maint Stairwell	PCM Air	0.001 Fibers/cc	0.010 fibers/cc
6/20/2017	Stadium Maint Stairwell	PCM Air	< 0.001 Fibers/cc	0.010 fibers/cc
6/20/2017	Stadium Maint Stairwell	PCM Air	< 0.001 Fibers/cc	0.010 fibers/cc
6/20/2017	Stadium Maint Stairwell	PCM Air	< 0.001 Fibers/cc	0.010 fibers/cc
6/23/2017	Room C-212	TEM Air	< 19 Structures/mm	70 Structures/mm
6/23/2017	Room C-213	TEM Air	< 19 Structures/mm	70 Structures/mm
6/23/2017	Room C-214	TEM Air	< 19 Structures/mm	70 Structures/mm
6/23/2017	Roof Access by Rm C-212	TEM Air	< 7.6 Structures/mm	70 Structures/mm
6/27/2017	B-Wing, Old Wrestling Rm	TEM Air	< 19 Structures/mm	70 Structures/mm
6/27/2017	B-Wing, 2nd Floor Hallway	TEM Air	< 19 Structures/mm	70 Structures/mm
6/27/2017	B-Wing, 2nd Flr, Side Office	TEM Air	< 19 Structures/mm	70 Structures/mm
7/20/2017	A-Wing Crawl Space, North	PCM Air	0.004 Fibers/cc	0.010 fibers/cc
7/20/2017	A-Wing Crawl Space, South	PCM Air	< 0.002 Fibers/cc	0.010 fibers/cc
7/21/2017	B-Wing Small Locker Rm	TEM Air	< 13 Structures/mm	70 Structures/mm
7/21/2017	Athletic Director Office	TEM Air	< 13 Structures/mm	70 Structures/mm
7/21/2017	B-Wing South Stairwell	TEM Air	< 13 Structures/mm	70 Structures/mm
7/21/2017	B-Wing Book Room	TEM Air	< 13 Structures/mm	70 Structures/mm
7/21/2017	Kitchen Dry Storage Room	TEM Air	< 13 Structures/mm	70 Structures/mm
7/27/2017	Storage by B-Wing S. Entrance	TEM Air	< 13 Structures/mm	70 Structures/mm
7/27/2017	B-Wing 1st Floor Hall	TEM Air	< 13 Structures/mm	70 Structures/mm
7/27/2017	B-Wing, North Stairwell	TEM Air	< 13 Structures/mm	70 Structures/mm
7/27/2017	Cafeteria, Doorway to Kitchen	TEM Air	< 13 Structures/mm	70 Structures/mm
7/27/2017	Cafeteria, Center	TEM Air	< 13 Structures/mm	70 Structures/mm
7/27/2017	Cafeteria, Corner near Storage	TEM Air	< 13 Structures/mm	70 Structures/mm
7/27/2017	Teacher's Lunch Room	TEM Air	< 13 Structures/mm	70 Structures/mm
7/27/2017	Kitchen Office	TEM Air	< 13 Structures/mm	70 Structures/mm
8/10/2017	B-Wing First Floor Hallway	PCM Air	0.004 Fibers/cc	0.010 fibers/cc
8/10/2017	B-Wing First Floor Hallway	PCM Air	< 0.002 Fibers/cc	0.010 fibers/cc
8/10/2017	B-Wing First Floor Hallway	PCM Air	0.003 Fibers/cc	0.010 fibers/cc
8/10/2017	B-Wing First Floor Hallway	PCM Air	0.005 Fibers/cc	0.010 fibers/cc
8/10/2017	B-Wing First Floor Hallway	PCM Air	0.003 Fibers/cc	0.010 fibers/cc
9/7/2017	Hall by Room A-125	Dust - Air	< 0.35 mg/m ³	5.0 mg/m ³
9/7/2017	Hall by Room A-203	Dust - Air	< 0.35 mg/m ³	5.0 mg/m ³
9/7/2017	Hall by Room C-109	Dust - Air	< 0.36 mg/m ³	5.0 mg/m ³
9/7/2017	Hall by Room C-210	Dust - Air	< 0.37 mg/m ³	5.0 mg/m ³

Central/Middle School

Date	Location	Sample Type	Result	Clearance Criteria
7/5/2017	Rotunda Work Area	TEM Air	< 13 Structures/mm	70 Structures/mm
7/5/2017	Rotunda Work Area	TEM Air	< 13 Structures/mm	70 Structures/mm
7/5/2017	Rotunda Work Area	TEM Air	< 13 Structures/mm	70 Structures/mm
7/5/2017	Rotunda Work Area	TEM Air	< 13 Structures/mm	70 Structures/mm
7/5/2017	Rotunda Work Area	TEM Air	< 13 Structures/mm	70 Structures/mm
7/7/2017	Stairwell Work Area	TEM Air	< 15 Structures/mm	70 Structures/mm
7/7/2017	Stairwell Work Area	TEM Air	< 15 Structures/mm	70 Structures/mm
7/7/2017	Stairwell Work Area	TEM Air	< 15 Structures/mm	70 Structures/mm
7/7/2017	Stairwell Work Area	TEM Air	< 15 Structures/mm	70 Structures/mm
7/7/2017	Stairwell Work Area	TEM Air	< 15 Structures/mm	70 Structures/mm
7/7/2017	Cafeteria Area #3	TEM Air	< 15 Structures/mm	70 Structures/mm
7/7/2017	Cafeteria Area #3	TEM Air	< 15 Structures/mm	70 Structures/mm
7/7/2017	Cafeteria Area #3	TEM Air	15 Structures/mm	70 Structures/mm
7/7/2017	Cafeteria Area #4	TEM Air	< 15 Structures/mm	70 Structures/mm
7/7/2017	Cafeteria Area #5	TEM Air	< 15 Structures/mm	70 Structures/mm
7/11/2017	Room 2 Storage	TEM Air	< 15 Structures/mm	70 Structures/mm
7/11/2017	Room 2 Storage	TEM Air	< 15 Structures/mm	70 Structures/mm
7/11/2017	Room 2 Storage	TEM Air	< 15 Structures/mm	70 Structures/mm
7/11/2017	Room 2 Storage	TEM Air	< 15 Structures/mm	70 Structures/mm
7/11/2017	Room 2 Storage	TEM Air	< 15 Structures/mm	70 Structures/mm
7/12/2017	Cafeteria Area #1	TEM Air	31 Structures/mm	70 Structures/mm
7/12/2017	Cafeteria Area #1	TEM Air	77 Structures/mm	70 Structures/mm
7/12/2017	Cafeteria Area #1	TEM Air	46 Structures/mm	70 Structures/mm
7/12/2017	Cafeteria Area #1	TEM Air	31 Structures/mm	70 Structures/mm
7/12/2017	Cafeteria Area #1	TEM Air	15 Structures/mm	70 Structures/mm
7/26/2017	Room 104	PCM Air	0.003 Fibers/cc	0.010 fibers/cc
7/26/2017	Room 108	PCM Air	0.004 Fibers/cc	0.010 fibers/cc
7/26/2017	Room 114	PCM Air	0.003 Fibers/cc	0.010 fibers/cc
7/26/2017	Room 112	PCM Air	0.005 Fibers/cc	0.010 fibers/cc
7/26/2017	Cafeteria by Boiler Room	PCM Air	0.008 Fibers/cc	0.010 fibers/cc
7/26/2017	Room 53	PCM Air	0.003 Fibers/cc	0.010 fibers/cc
8/3/2017	Room 53	PCM Air	0.005 Fibers/cc	0.010 fibers/cc
9/7/2017	Middle School Cafeteria	Dust - Air	0.49 mg/m ³	5.0 mg/m ³
9/7/2017	Rotunda	Dust - Air	< 0.30 mg/m ³	5.0 mg/m ³
9/7/2017	Hall by Room 114	Dust - Air	< 0.32 mg/m ³	5.0 mg/m ³
9/7/2017	Hall by Room 273	Dust - Air	< 0.33 mg/m ³	5.0 mg/m ³

Haddon Elementary School

Date	Location	Sample Type	Result	Clearance Criteria
7/6/2017	2nd Floor Work Area	TEM Air	< 13 Structures/mm	70 Structures/mm
7/6/2017	2nd Floor Work Area	TEM Air	< 13 Structures/mm	70 Structures/mm
7/6/2017	2nd Floor Work Area	TEM Air	< 13 Structures/mm	70 Structures/mm
7/6/2017	2nd Floor Work Area	TEM Air	< 13 Structures/mm	70 Structures/mm
7/6/2017	2nd Floor Work Area	TEM Air	< 13 Structures/mm	70 Structures/mm
7/12/2017	Room 102	TEM Air	< 16 Structures/mm	70 Structures/mm
7/12/2017	Room 102	TEM Air	< 16 Structures/mm	70 Structures/mm
7/12/2017	Room 102	TEM Air	< 16 Structures/mm	70 Structures/mm
7/12/2017	Room 102	TEM Air	< 16 Structures/mm	70 Structures/mm
7/12/2017	Room 102	TEM Air	< 16 Structures/mm	70 Structures/mm
7/13/2017	1st Floor Girl's Room	TEM Air	< 16 Structures/mm	70 Structures/mm
7/13/2017	1st Floor Girl's Room	TEM Air	< 16 Structures/mm	70 Structures/mm
7/13/2017	1st Floor Girl's Room	TEM Air	< 16 Structures/mm	70 Structures/mm
7/13/2017	1st Floor Girl's Room	TEM Air	< 16 Structures/mm	70 Structures/mm
7/13/2017	1st Floor Girl's Room	TEM Air	< 16 Structures/mm	70 Structures/mm
7/18/2017	Main Office	TEM Air	< 13 Structures/mm	70 Structures/mm
7/18/2017	Main Office	TEM Air	< 13 Structures/mm	70 Structures/mm
7/18/2017	Main Office	TEM Air	< 13 Structures/mm	70 Structures/mm
7/18/2017	Main Office	TEM Air	< 13 Structures/mm	70 Structures/mm
7/18/2017	Main Office	TEM Air	< 13 Structures/mm	70 Structures/mm
7/18/2017	Principal's Office	TEM Air	< 13 Structures/mm	70 Structures/mm
7/18/2017	Principal's Office	TEM Air	< 13 Structures/mm	70 Structures/mm
7/18/2017	Principal's Office	TEM Air	< 13 Structures/mm	70 Structures/mm
7/18/2017	Principal's Office	TEM Air	< 13 Structures/mm	70 Structures/mm
7/18/2017	Principal's Office	TEM Air	< 13 Structures/mm	70 Structures/mm
7/18/2017	Principal's Office	TEM Air	< 13 Structures/mm	70 Structures/mm
8/30/2017	Art Room	TEM Air	< 20 Structures/mm	70 Structures/mm
9/7/2017	Hall by Room 110	Dust - Air	0.52 mg/m ³	5.0 mg/m ³
9/7/2017	Ground Fl Hall by Teacher's Rm	Dust - Air	0.33 mg/m ³	5.0 mg/m ³
9/7/2017	Hall by Room 206	Dust - Air	0.32 mg/m ³	5.0 mg/m ³
9/7/2017	Hall by Room 202	Dust - Air	< 0.30 mg/m ³	5.0 mg/m ³

Tatem Elementary School

Date	Location	Sample Type	Result	Clearance Criteria
8/8/2017	2nd Floor Small Instruction	TEM Air	< 20 Structures/mm	70 Structures/mm
9/7/2017	All Purpose Room	Dust - Air	< 0.32 mg/m ³	5.0 mg/m ³
9/7/2017	Library	Dust - Air	< 0.33 mg/m ³	5.0 mg/m ³
9/7/2017	Hall by Room 209	Dust - Air	< 0.34 mg/m ³	5.0 mg/m ³
9/7/2017	Hall by Room 302	Dust - Air	< 0.34 mg/m ³	5.0 mg/m ³